



Contamination Monitor for Surface of Hand and Feet

| Nuclear Radiation Detector

☰ Details Info

Specification

type of detector	6 proportional counting tubes which are flat and flow gas type
type of monitoring rays	α 、 β
displaying unit	Bq/cm ² adn cps
sensitive area of the detector	hand 300 cm ² , foot 450 cm ² ; total area is about 2000 cm ²
the efficiency(to α 、 β) \geq 30%	



Head Office :1600 AVENUE DE LORIMIER BUREAU, 384 MONTRÉAL (QUÉBEC) CANADA H2K3W8 USAOffice:128 W SUFFLOK AVE,CENTRAL ISLIP,11722 N
Middle east & Africa Office : warehouse 9 /shed 9, Technology park P.O. Box 54806 RAK FZE , UAE



Email Us At: